Queen Isabella Memorial Causeway Structural Repairs

CSJ: 0031-04-065



Project Fact Sheet

* Project Scope of Work: Concrete Structural Repair, Cleaning

and Sealing Joints, Beam End

Repair, Column Fiber Wrap, Railing

Retrofit, and Silane Treatment

* Project Cost: \$ 2,000,000.00 (Engineer's Est.)

* Letting Date: July 2012

* Contract Time: 14 months

Queen Isabella Memorial Causeway

The Queen Isabella Memorial Causeway is a safe bridge. The work being performed in this contract is part of continued preventive maintenance and remediation strategies to maintain the bridge's extended service life.

Condition and Service Life Assessment (08/2009)



QUEEN ISABELLA MEMORIAL CAUSEWAY Condition and Service Life Assessment

South Padre Island, Texas



Final Report August 25, 2009 WJE No. 2008.5102.1



Prepared for:
Mr. Rex Costley
Pharr District Bridge Engineer
Texas Department of Transportation
600 W US Expressway 83
Pharr, TX 78577-1231

Prepared by:
Wiss, Janney, Elstner Associates, Inc.
TBPE Certification of Registration No. 0093
13581 Pond Springs Road Suite 107
Austin, Texas 78729
512.835.0940 tel | 512.835.6268 fax


Existing Conditions

- * Deck has minor to moderate transverse cracking.
- * Majority of armor joints contain minor to moderate plate deformation.
- * Exposed beam strands are corroding.
- * Caps and diaphrams have spalls throughout the bridge with exposed reinforcement.
- * Majority of railing has corroded anchor bolts and so


Span #1 WB Underside Bridge Deck Spalled concrete with exposed reinforcement.




Armor Joint Throughout Bridge Plate deformation at anchor stud locations.




End Diaphram – Various Locations Cracked diaphram with exposed reinforcement.




Beam End at Various Locations
Deteriorated epoxy coating and
exposed/corroded strands.




Beam End at Various Locations
Deteriorated epoxy coating and
exposed/corroded strands.



Bent #26 Cracked Column Minor map cracking along column.




Existing Rail Connection - Typical Existing anchor bolts and hardware severely corroded.




Maintenance Improvements

- * Remove deficient deck and replace with new. Span #1 (WB Side) will be removed and replaced.
- * Remove failed armor joints and replace with new. All existing joints shall be cleaned and sealed.
- * Repair spalled concrete areas (beams, diaphrams, and caps) with approved concrete patch material.
- * Remove existing epoxy coating at beam ends and apply surface treatment the surface area of the beam.
- * Remove existing aluminum posts and anchor new steel posts into concrete pedestal.


US 281 SBML @ BUS 281 Existing deck removal




US 83 @ Arroyo Dolores Completed deck repair and cleaning and sealing joint.




Completed Concrete Structure Repairs (Diaphrams)




Completed Concrete Structure Repairs (Beam)



Protective Beam End Pre-Stressing strands covered.





Contractor Operations

Work to be done on **TOP** of the bridge:

- * For concrete deck removal and armor joint replacement requires a one lane closure stationary.
- * Work shall be limited to November 1st to end of January.
- * Railing retrofit requires a one lane closure and will be picked up at the end of the week.

Work to be done from **BELOW** the bridge:

- * Limited to movable working platforms, and bucket lifts resting on barges.
- * Work from below can begin at any time.

Contractor Operations

TxDOT Snooper Truck Equipment utilized to perform inspection and address repair needs.



Project Schedule

Bids Received

Pre-Construction Meeting

Initial Schedule

Begin Work On Top

Begin Work Below

Completion of Work

July 2012

August 2012 (Tentative)

14 Months

November 2012 (Tentative)

September 2012 (Tentative)

December 2013

(No lane closures during major holidays and events)

TxDOT's Investment

Work Performed From 2001 to Present	
2001 Emergency Repairs	\$ 5.9 M
2003 Cathodic Protection	\$ 3.5 M
2003 Early Warning Protection	\$ 0.9 M
2003 Pier Protection	\$ 12.3 M
2004 Cathodic Protection	\$ 1.3 M
2007 Dolphin and Fender Repairs	\$ 1.1 M
2010 Painting, Steel and Cathodic Protection	\$ 4.3 M
2010 Illumination Pole Replacement	\$ 0.7 M
2011 Fender Repairs	\$ 0.3 M
2001 to Present Totals	\$ 30.3 M